


- BRS:
 - Pending
 - Active
 - L3: (50) 2 and (step-down or (step adj down))
 - L5: (42) 3 and time and ((reducS4 or lowerS3 or decr
 - L2: (173) autotransformer and tap and ((voltage and c
 - L11: (13) 10 and synchronizS5
 - L10: (34) 2 and (zero-crossing or (zero adj crossing))
 - Failed
 - Saved
 - Favorites
 - Tagged (0)
 - UDC
 - Queue
 - Trash

Search List Browse Queue Clear

DBs US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB

Default operator: OR

☒ Plurals ☒ Highlight all hit terms initially



BRS form IS&R form Image Text HTML

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Er	Erro
1	BRS	L3	50	2 and (step-down or (step adj down))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/21 16:39			
2	BRS	L5	42	3 and time and ((reducS4 or lowerS3 or decreasS3) near2 voltage)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/21 17:04			
3	BRS	L2	173	autotransformer and tap and ((voltage and current) near2 (detectS3 or sensS3 or measurS5)) and pulsS3 and switchS3	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/21 17:04			
4	BRS	L11	13	10 and synchronizS5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/21 17:05			
5	BRS	L10	34	2 and (zero-crossing or (zero adj crossing))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	2007/06/21 17:43			



- ☐ Drafts
- ☐ Pending
- ☒ **Active**
 - ☒ L1: (1) ((voltage near2 controlS4) and (multiple near2 tap
 - ☒ L2: (1) ((voltage near2 controlS4) and (load or lamp) and
 - ☒ L3: (1) ((method or process) and (voltage near2 controlS
- ☐ Failed
- ☐ Saved
- ☐ Favorites
- ☐ Tagged (0)
- ☐ UDC
- ☐ Queue
- ☐ Trash

Search:

DBs: US-PGPUB

☒ PluralsDefault operator: ☒ Highlight all hit terms initially

BRS form IS&R form Image Text HTML

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Er	Error
1	BRS	L1	1	((voltage near2 controlS4) and (multiple near2 tap) and step-down and autotransformer and (AC or (alternating adj current)) and ((voltage and current) near2 (detectS3 or sensS3 or measurS5)) and (pulse near2 (forming or generating or producing)) and (command near2 signal) and controller and switch and selectS5 and associated and period and time and turnS3 and ((reducS4 or lowerS3 or decreasS3) near2 voltage) and terminals).clm.	US-PGPUB	2007/06/21 18:04			
2	BRS	L2	1	((voltage near2 controlS4) and (load or lamp) and (multiple near2 tap) and step-down and autotransformer and ((voltage and current) near2 (detectS3 or sensS3 or measurS5)) and (pulsS3 near2 (forming or generating or producing)) and (command near2 signal) and controlS4 and switchS3 and determinS5 and zero-crossing and point and instantaneous and variation and synchronizS6).clm.	US-PGPUB	2007/06/21 18:08			
3	BRS	L3	1	((method or process) and (voltage near2 controlS4) and (load or lamp) and (multiple near2 tap) and step-down and autotransformer and ((voltage and current) near2 (detectS3 or sensS3 or measurS5)) and (pulsS3 near2 (forming or generating or producing)) and (command near2 signal) and controlS4 and switchS3 and determinS5 and zero-crossing and point and instantaneous and variation and synchronizS6).clm.	US-PGPUB	2007/06/21 18:08			